

# Energy performance certificate (EPC)

97, Seaview Drive  
BELFAST  
BT15 3ND

Energy rating

E

Valid until:

4 December 2028

Certificate number:

9178-2904-0525-9208-8851

Property type

end-terrace house

Total floor area

52 square metres

## Energy rating and score

This property’s current energy rating is E. It has the potential to be D.

[See how to improve this property’s energy efficiency.](#)

Score	Energy rating	Current	Potential
92+	A		
81-91	B		
69-80	C		
55-68	D		64 D
39-54	E	42 E	
21-38	F		
1-20	G		

The graph shows this property’s current and potential energy rating.

**Properties get a rating from A (best) to G (worst) and a score.** The better the rating and score, the lower your energy bills are likely to be.

For properties in Northern Ireland:

the average energy rating is D  
the average energy score is 60

## Breakdown of property’s energy performance

### Features in this property

Features get a rating from very good to very poor, based on how energy efficient they are. Ratings are not based on how well features work or their condition.

Assumed ratings are based on the property's age and type. They are used for features the assessor could not inspect.

Feature	Description	Rating
Wall	Cavity wall, as built, no insulation (assumed)	Poor
Roof	Pitched, 200 mm loft insulation	Good
Window	Fully double glazed	Average
Main heating	Boiler and radiators, oil	Average
Main heating control	Programmer, no room thermostat	Very poor
Hot water	From main system, no cylinder thermostat	Poor
Lighting	Low energy lighting in 43% of fixed outlets	Average
Floor	Solid, no insulation (assumed)	N/A
Secondary heating	None	N/A

### Primary energy use

The primary energy use for this property per year is 370 kilowatt hours per square metre (kWh/m2).

### Additional information

Additional information about this property:

- Cavity fill is recommended

### Environmental impact of this property

This property’s current environmental impact rating is F. It has the potential to be D.

Properties get a rating from A (best) to G (worst) on how much carbon dioxide (CO2) they produce each year. CO2 harms the environment.

An average household produces	6 tonnes of CO2
-------------------------------	-----------------

This property produces	5.0 tonnes of CO2
------------------------	-------------------

This property’s potential production	3.1 tonnes of CO2
--------------------------------------	-------------------

You could improve this property’s CO2 emissions by making the suggested changes. This will help to protect the environment.

Environmental impact ratings are based on assumptions about average occupancy and energy use. They may not reflect how energy is consumed by the people living at the property.

### Changes you could make

Step	Typical installation cost	Typical yearly saving
1. Cavity wall insulation	£500 - £1,500	£109
2. Add additional 80 mm jacket to hot water cylinder	£15 - £30	£10
3. Low energy lighting	£20	£20
4. Hot water cylinder thermostat	£200 - £400	£18
5. Heating controls (room thermostat and TRVs)	£350 - £450	£80
6. Replacement glazing units	£1,000 - £1,400	£24
7. Floor insulation (solid floor)	£4,000 - £6,000	£29
8. Solar water heating	£4,000 - £6,000	£36
9. Gas condensing boiler	£3,000 - £7,000	£67
10. Solar photovoltaic panels	£5,000 - £8,000	£288

## Paying for energy improvements

You might be able to get a grant from the [Boiler Upgrade Scheme \(https://www.gov.uk/apply-boiler-upgrade-scheme\)](https://www.gov.uk/apply-boiler-upgrade-scheme). This will help you buy a more efficient, low carbon heating system for this property.

## Estimated energy use and potential savings

Based on average energy costs when this EPC was created:

Estimated yearly energy cost for this property	£701
--	------

Potential saving if you complete every step in order	£262
--	------

The estimated cost shows how much the average household would spend in this property

for heating, lighting and hot water. It is not based on how energy is used by the people living at the property.

### Heating use in this property

Heating a property usually makes up the majority of energy costs.

### Potential energy savings by installing insulation

The assessor did not find any opportunities to save energy by installing insulation in this property.

## Contacting the assessor and accreditation scheme

This EPC was created by a qualified energy assessor.

If you are unhappy about your property's energy assessment or certificate, you can complain to the assessor directly.

If you are still unhappy after contacting the assessor, you should contact the assessor's accreditation scheme.

Accreditation schemes are appointed by the government to ensure that assessors are qualified to carry out EPC assessments.

### Assessor contact details

Assessor's name	Barry Oneill
Telephone	07763922223
Email	<a href="mailto:barry@elanenvironmental.com">barry@elanenvironmental.com</a>

### Accreditation scheme contact details

Accreditation scheme	Stroma Certification Ltd
Assessor ID	STRO005086
Telephone	0330 124 9660
Email	<a href="mailto:certification@stroma.com">certification@stroma.com</a>

### Assessment details

Assessor's declaration	No related party
Date of assessment	4 December 2018
Date of certificate	5 December 2018
Type of assessment	<a href="#">RdSAP</a>

---