# **Energy performance certificate** (EPC)



## **Property type**

Mid-terrace house


#### **Total floor area**

109 square metres

#### **Energy efficiency rating for this property**

This property's current energy rating is D. It has the potential to be C.

See how to improve this property's energy performance.



The graph shows this property's current and potential energy efficiency.

Properties are given a rating from A (most efficient) to G (least efficient).

Properties are also given a score. The higher the number the lower your fuel bills are likely to be.

The average energy rating and score for a property in Northern Ireland are D (60).

#### Breakdown of property's energy performance

This section shows the energy performance for features of this property. The assessment does not consider the condition of a feature and how well it is working.

Each feature is assessed as one of the following:

- very good (most efficient)
- good
- average
- poor
- very poor (least efficient)

When the description says "assumed", it means that the feature could not be inspected and an assumption has been made based on the property's age and type.

Feature	Description	Rating
Wall	Cavity wall, as built, no insulation (assumed)	Poor
Roof	Flat, no insulation (assumed)	Very poor
Window	Fully double glazed	Good
Main heating	Boiler and radiators, oil	Average
Main heating control	Programmer, room thermostat and TRVs	Good

Feature	Description	Rating
Hot water	From main system	Average
Lighting	Low energy lighting in 94% of fixed outlets	Very good
Floor	Solid, no insulation (assumed)	N/A
Secondary heating	None	N/A

# Primary energy use

The primary energy use for this property per year is 207 kilowatt hours per square metre (kWh/m2).

What is primary energy use?

#### **Environmental impact of this property**

One of the biggest contributors to climate change is carbon dioxide (CO2). The energy used for heating, lighting and power in our homes produces over a quarter of the UK's CO2 emissions.

## An average household produces

6 tonnes of CO2

## This property produces

5.9 tonnes of CO2

## This property's potential production

4.1 tonnes of CO2

By making the <u>recommended changes</u>, you could reduce this property's CO2 emissions by 1.8 tonnes per year. This will help to protect the environment.

Environmental impact ratings are based on assumptions about average occupancy and energy use. They may not reflect how energy is consumed by the people living at the property.

#### How to improve this property's energy performance

Making any of the recommended changes will improve this property's energy efficiency.

If you make all of the recommended changes, this will improve the property's energy rating and score from D (59) to C (72).

What is an energy rating?

# **Recommendation 1: Cavity wall insulation**

Cavity wall insulation

## Typical installation cost

£500 - £1,500

Potential energy

rating

# Typical yearly saving

£62

## Potential rating after carrying out recommendation 1

62 | D

# Recommendation 2: Flat roof or sloping ceiling insulation

Flat roof or sloping ceiling insulation

## Typical installation cost

£850 - £1,500

## Typical yearly saving

£202

## Potential rating after carrying out recommendations 1 and 2

72 | C

# **Recommendation 3: Solar water heating**

Solar water heating

# Typical installation cost

£4,000 - £6,000

# Typical yearly saving

#### Potential rating after carrying out recommendations 1 to 3

73 | C

# Recommendation 4: Solar photovoltaic panels, 2.5 kWp

Solar photovoltaic panels

## Typical installation cost

£3,500 - £5,500

## Typical yearly saving

£315

## Potential rating after carrying out recommendations 1 to 4

82 | B

# Paying for energy improvements

Find energy grants and ways to save energy in your home. (https://www.gov.uk/improve-energy-efficiency)

Estimated energy use and potential savings

## Estimated yearly energy cost for this property

£946

## Potential saving

£264

The estimated cost shows how much the average household would spend in this property for heating, lighting and hot water. It is not based on how energy is used by the people living at the property.

The estimated saving is based on making all of the recommendations in how to improve this property's energy performance.

# Heating use in this property

Heating a property usually makes up the majority of energy costs.

## Potential energy savings by installing insulation

The assessor did not find any opportunities to save energy by installing insulation in this property.

#### Contacting the assessor and accreditation scheme

This EPC was created by a qualified energy assessor.

If you are unhappy about your property's energy assessment or certificate, you can complain to the assessor directly.

If you are still unhappy after contacting the assessor, you should contact the assessor's accreditation scheme.

Accreditation schemes are appointed by the government to ensure that assessors are qualified to carry out EPC assessments.

# **Assessor contact details**

#### Assessor's name

Declan Heggarty

#### **Telephone**

07595 362912

#### **Email**

declan@nienergyrating.com

## Accreditation scheme contact details

#### Accreditation scheme

Elmhurst Energy Systems Ltd

#### **Assessor ID**

EES/024866

#### **Telephone**

01455 883 250

#### **Email**

enquiries@elmhurstenergy.co.uk

# **Assessment details**

#### Assessor's declaration

No related party

#### Date of assessment

9 April 2021

#### Date of certificate

# Type of assessment



► RdSAP

#### Other certificates for this property

If you are aware of previous certificates for this property and they are not listed here, please contact us at <a href="mailto:mhclg.digital-services@communities.gov.uk">mhclg.digital-services@communities.gov.uk</a>, or call our helpdesk on 020 3829 0748.

There are no related certificates for this property.